

PhotoSlate Heat Transfer Instructions

Heat Transfer Instructions

Temperature: 400 degrees

Press Time: 9 minutes

Pressure: Heavy

Step By Step

- 1) Place a clean sheet of paper on the bottom of the press.
- 2) Secure transfer to PhotoSlate with heat tape.
- 3) Place PhotoSlate, face up on the heat press.
- 4) Cover with green heat conductive rubber.
- 5) Press for 4 1/2 minutes. Rotate PhotoSlate 180 degrees. Press additional 4 1/2 minutes.

ACPTechnologies

800-741-2551 • www.acp.com

425 Cross Street, Suite 213

Punta Gorda, FL 33950