

## Vapor Mask Heatpress Instructions

1. Lint roll the mask to remove any lint from image area.
2. Place a clean sheet of plain paper on the heat press table.
3. Place the mask (polyester side up) on the paper.
4. Place the transfer face down on the mask.
5. Place a clean sheet of plain paper on top.
6. Press at 385 degrees for 45 seconds

**\*Legal Disclaimer:** The Vapor Mask should not be used (1) in any medical setting or where significant exposure to liquid, bodily fluids is possible; (2) in a clinical setting of any type; or (3) around or near and high heat source or flammable liquid. ACP Technologies makes no warranties, either express or implied, that the face cover prevents infection or the transmission of viruses or diseases.

**ACPTechnologies**

800-741-2551 • [www.acp.com](http://www.acp.com)

425 Cross Street, Suite 213

Punta Gorda, FL 33950